
Crystal Mountain Diesel Spill

November 2006

Standing on USTs Looking Towards Power Plant



Location



Valve Box from USTs to Generator Product Seeped into Vault



Test Pit next to power Plant Product Floating on Groundwater



Behind Power Plant NW Along Fence



Day Tank Over Flow Discharges to Ground



Generator Day (Fuel) Tank



Behind Generator Plant- (Looking NE) Groundwater 1 Ft. Deep w/ Product



Drainage Ditch Behind Generator Plant (Looking SE)



Drainage Ditch from Behind Generator Plant (Looking South)



Coffer Dam in Action



Drainage Area next to Crystal Mt. Blvd



Silver Creek East of Site



Utility/Power Line Road Looking NW



Diesel Ran Over Ground Down Utility/Power Line Road (Looking NW)



Utility/Power Line Road Impact



1000 Ft. Down Utility/Power Line Road – Earth Berm Constructed

(Looking SE)



Utility/Power Line Road Impact



Backer Boxes for Contaminated Debris



Baker Tank for Recovered Product Place Next to Baker Boxes

